Accessories

Weight (lbs.)	0.0500

R-108

OBSOLETE-Octoport Pocket Stamp


S
input
O
output
must be
plugged
1
2
8
not used
7
3
E
exhaust
6
4
5
do not plug
auxiliary pilot
P
pilot
input
must not
be plugged
or restricted
Example