




Pneumatic Sensors

1022

Max PSI	4-10 psig
Medium	Air
Weight (lbs.)	0.1000



Proximity Sensor, Non-Contact, #10-32

