



Pneumatic Sensors

1030



Gap Sensor, Non-Contact, #10-32

Max PSI	05-5 psig
Medium	Air
Temperature Range	32 to 230°F
Weight (lbs.)	0.0900

